

# SAFETY DATA SHEET

## JET0515: FLUSHING SOLUTION FOR OIL BASED INKS

### 1 IDENTIFICATION OF THE SUBSTANCE/PREPARATION AND THE COMPANY

PRODUCT NAME: JET0515: FLUSHING SOLUTION FOR OIL BASED INKS  
PART No.: JET0515

### 2 COMPOSITION/INFORMATION ON INGREDIENTS

INGREDIENT NAME	CAS No.	CONTENTS	HEALTH (class)	RISK (R No.)
PETROLEUM DISTILLATE	64742-46-7	60-100 %	Xn	65

### 3 HAZARDS IDENTIFICATION

Harmful: may cause lung damage if swallowed.

### 4 FIRST AID MEASURES

**GENERAL:** Remove victim immediately from source of exposure. If breathing stops, provide artificial respiration. Get medical attention immediately!

**INHALATION:** DO NOT INDUCE VOMITING! NEVER MAKE AN UNCONSCIOUS PERSON VOMIT OR DRINK FLUIDS! Remove victim immediately from source of exposure. Immediately to hospital, even if discomfort is gone.

**INGESTION:** Remove victim immediately from source of exposure. Do not induce vomiting. If vomiting occurs, the head should be kept low so that stomach vomit doesn't enter the lungs. Danger of aspiration and development of chemical pneumonia. NEVER MAKE AN UNCONSCIOUS PERSON VOMIT OR DRINK FLUIDS! Provide rest, warmth and fresh air. Get medical attention immediately!

**SKIN:** Remove affected person from source of contamination. Wash off promptly and flush contaminated skin with water. Promptly remove clothing if soaked through and flush skin with water. Get medical attention promptly if symptoms occur after washing.

**EYES:** Remove victim immediately from source of exposure. Make sure to remove any contact lenses from the eyes before rinsing. Promptly wash eyes with plenty of water while lifting the eye lids. Continue to rinse for at least 15 minutes. Contact physician if irritation persists.

### 5 FIRE FIGHTING MEASURES

**EXTINGUISHING MEDIA:** Fire can be extinguished using: Foam. Dry chemicals, sand, dolomite etc. DO NOT use water if avoidable.

**SPECIAL FIRE FIGHTING PROCEDURES:**

Avoid water in straight hose stream; will scatter and spread fire. Containers close to fire should be removed immediately or cooled with water. Cool containers exposed to flames with